

BULLETIN Nº 3

Senior & Junior Update

Section F; General Rules

Point 2,

2.3

The teeth structure on the rear sprocket must be manufactured in the same shape and tooth profile as the originally Tillotson supplied sprocket, as shown in image below.



This modification must be applied immediately.

Chiva, September 8th 2024, at 8:45

The Stewards